DAlI PRO v2.2.6.16710 (FW 3.72)

ChangeLog:
- Add Multi selection of ECG combinations
- Add Support for Turkey installations
- Add AutoSave function of the project (...[USER]\Documents\OSRAM\DALI Professional 2\AutoSave)
- Add Simplified test-functionality for very large intstallations (faster, but without recall of previous light settings, in Settings menue)
- Add RGB with DT8
- Add RGBW combination (experimental only)
- Add Dimm to dark (--> 0,1% dimm level, not in app control & light regulation)
- Add MasterLight function (Using dim status of ECG for conditions)
- Add DALI communication test function (Tool icon in top bar)
- Update / extend Zone separator function
- Update / extend Step sequencer function
- Bug Fix (Using sensor in multiple functions)
- Bug Fix (Using more than 255 devices)
- Bug Fix (Astro function was only working if RGB enabled)
- Bug Fix (After power-cycle, some sensors were occasionally blocked)
- Bug Fix (Adjust timings to fix upload problems)
- Bug Fix (Occasionally controller could not by found by PC software, "Controller freeze" behaviour)
- Other minor bug fixes
- Improved stability