

Product

DALI PRO 2 IoT

EAN-010: 4062172114189

Release Notes

PCTool Version: 3.1.15.21721 **Date: October 5th, 2023**

- Changed: Limit for the regulation calibration sensor value from 1 % to 0.05 %
- Improved: DALI PRO 2 IoT file download
- Improved: DALI PRO 2 IoT reconnect after project file open
- Improved: DALI PRO RTC CON 4 KNX device search

PCTool Version: 3.1.13.20718 **Date: November 18th, 2022**

- Added: e-mail notification settings
- Added: MQTT settings
- Added: REST test dialog

PCTool Version: 3.1.12.20209 **Date: June 9th, 2022**

- Added: Emergency Light dialog
- Added: support of fast mapping (available only in Evaluation mode)
- Added: device service dialog (available only in Evaluation mode)

PCTool Version: 3.1.10.9728 **Date: January 28th, 2022**

- Added: support for Dutch
- Added: remote-access import/export files
- Added: remote-access enable/disable by e-mail
- Added: support for Italian
- Added: support of part 302 switch and slider
- Added: extended IoT device and lamp error monitoring
- Added: support for Spanish

PCTool Version: 3.1.9.19412 **Date: Oct 8th, 2021**

- Bug fix check connection
- Bug fix set to plug & play mode
- Add new language items for connection check (only English and German)
- Add error message for wrong password in virtual wiring file

PCTool Version: 3.1.7.19115 **Date: July 9th, 2021**

- Added: Support of DALI PRO 2 IoT LAN Interconnect

PC TOOL Version: 3.1.6.19023 **Date: June 23, 2021**

- Support of the updated version 1.6.x of the EM/MA gateway
- Added: Function for testing the DALI2 motion detectors and pushbutton configuration
- Added: Support of multiple GTINs
- Added: Display of the μ C FW version for the "service" access level
- Added: Property "DALI data" to identify ECGs that support PMD
- Optimization: DT8 RGBW scenes and TW configuration
- Bug fixing: Timers and switch-on behaviour • Bug fixing: some smaller improvements •
Bug fixing: Timers and switch-on behaviour

PC TOOL Version: 3.1.5.18814 **Date: April 14th, 2021**

- Contains FW 3.78 for DALI PRO CON 4 (RTC) for changeable dimming speed at long button press and bugfix for deactivation of motion detection at long button press
- For DALI PRO IoT device name is equal to host name (required minimum FW 3.1.3.x)
- Added: Chinese language support
- Added: Test function to check DALI 2 movement sensor configuration
- Added: DALI PRO IoT alternative device detection by local broadcast UDP (requires minimum FW 3.1.3.x)
- Added: Function to set dimming speed for long button press for DALI PRO CON 4 (RTC) (requires at least FW classic 3.78)

- Bug fixing: Project file download for DALI PRO IoT
- Bug fixing: FW update function DALI PRO CON 4 (RTC)

PC TOOL Version: 3.1.2.18303

Date: November 26th, 2020

- Other application controllers on the DALI line are now supported
- Possibility to generate a report with DALI group and scene configuration
- Includes FW 3.77 for DALI Pro classic
- Scene call in daylight simulation
- Slow mode for RGB sequence effect
- Bug fixes and improvements of DALI 2 sensor test functions
- Bug fix for interconnection of DALI PRO (classic) devices
- Bug fix in zone separator
- Bug fix in step sequencer
- Bug fix PMD memory bank 207
- LAN password icon for DALI PRO 2 IoT (not applicable)